

TO BE FILLED BY INSPECTING OFFICER  
(Assistant Engineer / Assistant Executive Engineer)

Name of School : MOULANA ABUL KALAM AZAD MEMORIAL ENGLISH

1. Name of the Officer : SUJA.K.K  
MEDIUM PUBLIC SCHOOL.

2. Location : VENTARAMOODU, ATTINGAL.

3. Period for which the certificate is issued : 2023-2024 Academic year.

4. Types of building : Permanent Three storied R.C.C. Building

5. Nature of defect if any

a) Foundation and basement

b) Superstructure

c) Doors and windows

d) Wood work wrought and put up

e) Roof

f) Flooring

g) Miscellaneous (Cracks if any)

31.00 x 9.50 x 3.60 - G.F

31.00 x 9.50 x 3.60 - F.F

31.00 x 9.50 x 3.60 - S.F

Nil

6. Any major defects noticed which will render the building unsafe in any manner

7. Whether maintenance work have been done properly

Yes

8. Whether the structure is sound or not for conducting classes.

The Structure is sound for conducting classes under normal weather conditions.

- Note :
- 1 The Stability of the structure should be examined also with reference to location altitude intensity of wind exposure to flood etc.
  - 2 Any additional observation deemed necessary for the Certificate, may be furnished separately with the Certificate.

Certified that the School was inspected by me on 10.05.2023 and found to be, fit / unfit to conduct classes for the period for the reasons stated above.

Place : Nellamad

Signature



Date : 10.05.2023.

Designation

ASSISTANT ENGINEER  
LSGD Section  
Nellanadu Grama Panchayat